



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name and Location	RFK charter school 4306 Blake rd SW		
Site Contact Name & Agency	NID providers	ESC File No.	NID E006
Date of Inspection	2-21-18	Start/End Time	10:55/11:00
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality		
Describe Present Phase of Construction	Stabilized		

Type of Inspection:

☒ Regular ☐ During storm event ☐ Post-storm event (> 0.5 inch) ☐ 311 / Complaint Response ☐ Follow-Up

Weather Information

Weather at time of this inspection?

Temperature: ~ 40 F°

☒ Clear ☐ Cloudy ☐ Rain ☐ Sleet ☐ Fog ☐ Snowing ☐ Windy

Has there been a storm event since the site was Permitted? ☒ Yes ☐ No

Amount: ☒ < 1/4" ☐ 1/4" to 3/4" ☐ > 3/4" ☐ Snow _____

Erosion & Sediment Control Inspection

Entrance / Track-Out

Sediment Controls / Silt Fence,
Inlet Protection, Wattles, etc.

Stabilized

Inspection Reports

Erosion Controls
Housekeeping/Pollutant Controls

Debris/Pollutants/Sediment in MS4
Notes

Is site being maintained in compliance with the Drainage Ordinance? ☒ Yes ☐ No

Signature

Date

Curtis C. Cherne

2-21-18