

# CITY OF ALBUQUERQUE



November 24, 2014

Verlyn Miller, PE  
Miller Engineering Consultants  
3500 Comanche NE Bldg. F  
Albuquerque, NM 87110

**Re:   RFK Charter School Auto Body Shop**  
**4300 Blake Rd. SW**  
**Request Permanent C.O. - Accepted**  
**Engineer's Stamp dated: 11-27-13 (N10D006)**  
**Certification dated: 11-19-14**

Dear Mr. Miller,

Based on the Certification received 11/19/2014, the site is acceptable for release of Certificate of Occupancy by Hydrology.

If you have any questions, you can contact me at 924-3695 or Rudy Rael at 924-3977.

PO Box 1293

Albuquerque

New Mexico 87103

Sincerely,

Curtis Cherne, P.E.  
Principal Engineer, Planning Dept.  
Development and Review Services

[www.cabq.gov](http://www.cabq.gov)

C:   RR/CC  
     email