



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Valle de Atrisco		
Location:	9901 Ceja Vista Rd SW		
Site Contact Name & Agency	Trevor/ Trevco Inc. trevor@trevco-inc.com	ESC File No.	P09E002D
		NPDES Id. No.	NMR1001TW/ NMR1001TV
Inspection Date:	08/17/20	Start/End Time:	0835/0900hrs
CoA Stormwater Inspector:	Timothy E. Sims		
Construction Phase:	vertical		
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25" <input type="checkbox"/> 311/Complaint <input checked="" type="checkbox"/> Follow Up

Weather at time of inspection?	Clear/ Windy	Temperature: ~	77*
Estimated date of last storm 0.25" or greater	7/25/2020		

Item Number	Deficiency/ Corrective Action		
	no issues observed		
	***Please provide latest SWPPP self-inspection report.		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date: 6/19/2020

Notes:	inspection conducted adhering to Covid-19 constraints

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 08/17/20