

City of Albuquerque Stormwater Construction Site Inspection Report

General Information						
Project Name:	Valle de Atrisco					
Location:	9901 Ceja Vista Rd SW					
Site Contact Name &	Trevor/ Trevco Inc.		ESC File No.	P09E002D		
Agency	505-23862	15	NPDES Id. No.		NMR1001TV	•
Inspection Date:	03/18/19	Start/End Time:	0830/0900hrs			
CoA Stormwater Inspector:		Timothy Sims, Stormwater Inspector				
Present Phase of	Foundations, footings					
Construction:						
Type of Inspection:	Regular	Storm Event	Post Storm	Event >0.25"	311/Complaint	x Follow Up
Weather at time of inspection?			Tempe	rature: ~	46*	
	Clear					
Has there been a storm event since site was Permitted?						
Clarify amount: (i.e <1/4" to >3/4"): Yes, >3			5, >3/4"			

Clarify amount: (i.e <1/4" to >3/4"):	Yes, >3/4"

Inspection				
		Maintenance		
CGP	BMP / Activity	or Corrective	Location and Notes	
Section	,	Action		
		Required		
1.5	Post a Notice			
2.2.1	Provide and maintain Natural buffer when Waters of the US <50ft.			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.4	Minimize sediment track out			

2.2.5	Manage stock piles			
2.2.6	minimize dust			
2.2.10	Protect storm drain inlets			
2.2.10	Protect storm drain inlets			
2.2.11	Minimize erosion of conveyance channels			
2.2.12	Sediment Basins			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.3.1	Equipment and vehicle fueling			
2.3.2	Equipment and vehicle washing			
2.3.3	Building material storage			
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage			
2.3.3	Construction and domestic wastes			
2.3.3	Construction and domestic wastes			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.4	Dewatering			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports	requested	Latest report Date:	

Notes: (City Inspector Use) Items in compliance can be left blank.

Maintenance or corrective actions are to be completed within seven (7) days.

Notes:	Please forward the latest self-inspection report

City of Albuquerque S	tormwater Inspector Signature and date:	
Contact information:	Contact information: Timothy Sims, 505-803-6155 or	
	tsims@cabq.gov	

¹ Construction General Permit (CGP)