

City of Albuquerque Stormwater Construction Site Inspection Report

General Information									
Project Nai	ne:	Valle de Atrisco							
Location:		9901 Ceja Vista Rd SW							
Site Contact Name &		Trevor/ Trevco Inc.		ESC File No.		P09E002D			
Agency		trevor@trevco-inc.com		NPDES Id. No.	NMF	R1001TW/ NMR1001TV			
Inspection	Date:	06/17/19 St	50/1030hrs						
CoA Stormwater Inspector: Timothy E. Sims									
	ction Phase:	vertical/ footings							
Type of Ir	nspection:	Regular Storm Event		Post Storm Event >0.25" 311/Complaint x Follow Up					
Weath	er at time of i	inspection?	Clea			rature: ~	77*		
Estimated	date of last s	storm 0.25" oi	r greater		5/11/2019				
Item									
			Deficien	cy/ Correctiv	e Action				
Number									
	all previous issues mitigated.								
	Thanks for cleaning up the recent concrete slobber on the ground at the second row of buidings,								
	also for staying on top of the domestic and construction waste Site looks good.								
2.1	Discharge off site?	(Y/N)	No						
4	Self Inspec	tion Reports		Latest rep	ort Date:	6/6/202	19		

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155