City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Valle de Atrisco								
Location:	9901 Ceja Vista Rd SW								
Site Contact Name & Agency	Trevor/ Trevco Inc.			ESC File No.	P09E002D				
	trevor@trevco-inc.com			NPDES Id. No.	NMR1001TW/ NMR1001TV				
Inspection Date:	09/11/19	Start/End Time:	0920/0925hrs						
CoA Stormwater Inspector:		Timothy E. Sims							
Construction Phase:	vertical/ footings								
Type of Inspection:	x	Regular		Storm Event		Post Storm Event >0.25"		311/Complaint	x Follow Up

Weather at time of inspection?	Clear	Temperature: ~	71*
Estimated date of last storm 0.25" or greater	7/7/2019		

Item Number	Deficiency/ Corrective Action			
	no issues observed. Thanks for staying on top of the domesitc waste. (water and sports drink bottles)			
	***Please provide latest SWPPP self-inspection report.			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports	requested	Latest report Date:	8/2/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date: Timothy E. Sims

Digitally signed by Timothy E. Sims
DN: cn=Timothy E. Sims, o=Stormwater Inspectionos, ou=Planning, email=tsims@cabq.gov, c=US
Date: 2019.09.12 08:42:37 -06'00'

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov 09/11/19