



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Valle de Atrisco		
Location:	9901 Ceja Vista Rd SW		
Site Contact Name & Agency	Trevor/ Trevco Inc. trevor@trevco-inc.com	ESC File No.	P09E002D
		NPDES Id. No.	NMR1001TW/ NMR1001TV
Inspection Date:	11/20/19	Start/End Time:	850
CoA Stormwater Inspector:	Timothy E. Sims		
Construction Phase:	vertical/ footings		
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Post Storm Event >0.25" ☐ 311/Complaint ☒ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	52*
Estimated date of last storm 0.25" or greater	10/4/2019		

Item Number	Deficiency/ Corrective Action		
	no issues observed. Thanks for staying on top of the domesitc waste. (water and sports drink bottles)		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 11/8/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 11/20/19