



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Ceja Vista Ph 1'				
Location:	Dennis Chavez & 98th St				
Site Contact Name & Agency	Allen William - Ceja Vista Ilc	ESC File No.	P09E002D_CV		
	ballen@westpacnm.com	NPDES Id. No.	NMR1002BE		
Inspection Date:	11/20/19	Start/End Time:	0830/0845hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	clear & grub				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Post Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	52*
Estimated date of last storm 0.25" or greater	10/4/2019		

Item Number	Deficiency/ Corrective Action		
1	Please provide NPDES posting for this site. Post sign visible to R.O.W.		
2	Track out pad requires maintenance.		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 11/8/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 11/20/19