



City of Albuquerque
Stormwater Construction Site
Inspection Report

General Information

Project Name and Location	Valle De Arisco Apartments 10010 Cesa Vista Rd SW		
Site Contact Name & Agency	Todd Coleman Valle De Arisco Arts, LLC	ESC File No. NPDES ID No.	P09E002B
Date of Inspection	11-30-18	Start/End Time	9:35 / 10:15
COA Inspector Name	Curtis Cherne, Stormwater Quality		
Describe Present Phase of Construction	grading		
Type of Inspection:	<input checked="" type="radio"/> Regular • During storm event • Post-storm event (> 0.25 inch) • 311 / Complaint Response • Follow-Up		

Weather Information

Weather at time of this inspection?	Temperature: ~ 45 F°
• Clear • <input checked="" type="radio"/> Cloudy • Rain • Sleet • Fog • Snowing • <input checked="" type="radio"/> Windy	
Has there been a storm event since the site was Permitted? • Yes • <input checked="" type="radio"/> No	
Amount: • < 1/4" • 1/4" to 3/4" • > 3/4" • Snow _____	

Inspection

CGP ¹ Section	BMP / Activity	Maintenance or Corrective Action Required	Location and Notes
1.5	Post a Notice	✓	no posting
2.2.1	Provide and maintain Natural buffer when Waters of the US < 50 ft		
2.2.3	Sediment control along any perimeter	✓	silt fence not buried north side east 150'
2.2.3	Sediment control along any perimeter	✓	require sediment BMP water tank area
2.2.3	Sediment control along any perimeter		tank spout, hose, valve leaking small screen
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.4	Minimize sediment track-out	✓	no track-out pad - minor/no track-out

2.2.5	Manage stockpiles		
2.2.6	Minimize Dust	✓	west east pod area sediment blowing off
2.2.10	Protect Storm Drain Inlets		
2.2.10	Protect Storm Drain Inlets		
2.2.11	Minimize erosion of conveyance channels		
2.2.12	Sediment Basins		
2.2.14	Stabilize exposed portions of the site.		
2.2.14	Stabilize exposed portions of the site.		
2.2.14	Stabilize exposed portions of the site.		
2.2.14	Stabilize exposed portions of the site.		
2.3.1	Equipment and Vehicle Fueling		
2.3.2	Equipment and Vehicle Washing		
2.3.3	Building Material Storage		
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage		
2.3.3	Construction and Domestic Wastes		
2.3.3	Construction and Domestic Wastes		
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.		
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.		
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.		
2.4	Dewatering		
2.1	Discharge off site?	• Yes • No	
4	Self-Inspection Reports	report	Latest Report Date:

Notes: (City Inspector Use) Items in compliance can be left blank.

¹ Construction General Permit (CGP)

Maintenance or corrective actions are to be completed within 7 days.

Notes:	Guzman - Dir
	Spoke w/ Tom Guzman Supv and water spoke with water tank down

City of Albuquerque Stormwater Inspector Signature and Date:

Curtis C. Cherne
Signature

11-30-10
Date

Contact Info: Curtis Cherne, 505-924-3420, ccherne@cabq.gov