



INSPECTIONS PLUS

General Permit SWPPP Inspection

Site Name:	<u>Ceja Vista Senior Apartments</u> <u>10001 Ceja Vista Rd SW, Albuquerque, NM 87121</u>	Inspector:	Jeff Hart
Permit #:	NMR10032D	Inspection Frequency:	Bi-weekly -
Date of Visit:	Jun 4, 2021, 11:42:02 AM	Last Rain Event Tuesday, June 1, 2021, 0.0"	Last Precipitation Friday, June 4, 2021, 0.07" 48h Forecast 19% Chance of Rain

Inspection Form Instructions

Review each question for this inspection carefully, then answer YES, NO, or N/A (not applicable). If any of the items below are out of compliance, press the "Add Action Item" button above to add a corrective action.

General Information

Inspector's Qualifications

Trained and work experience - see inspector qualification page in section 2 of the SWPPP.

Type of Inspection:

- ☒ **Regular** ☐ During storm event
☐ Post-storm event

Weather Information

Last Storm Event Information

For information on the last storm event, see the weather event information at the end of this inspection.

Weather at time of this inspection?

- ☒ **Clear** ☐ Cloudy ☐ Rain
☐ Sleet ☐ Snowing ☐ High Winds
☐ Partly Cloudy

Have any discharges occurred since the last inspection?

- ☐ Yes ☒ No

If yes, what did the water look like at the time of the discharge?

Are there any discharges at the time of this inspection?

- ☐ Yes ☒ No

If yes, what did the water look like at the time of the discharge?

Is a rain gauge installed on site?

- ☐ Yes ☒ No

If yes, where is it located?

Nearby gauge, NOAA, COCORHAS and Weather Underground monitored as secondary resources.

Has the Rain Event Page been filled out?

- ☒ Yes ☐ No



INSPECTIONS PLUS

General Permit SWPPP Inspection

Site Name:	<u>Ceja Vista Senior Apartments</u> <u>10001 Ceja Vista Rd SW, Albuquerque, NM 87121</u>	Inspector:	Jeff Hart
Permit #:	NMR10032D	Inspection Frequency:	Bi-weekly -
Date of Visit:	Jun 4, 2021, 11:42:02 AM	Last Rain Event Tuesday, June 1, 2021, 0.0"	Last Precipitation Friday, June 4, 2021, 0.07" 48h Forecast 19% Chance of Rain

Are there SDS sheets on site?

Yes

No

If yes, where are they located?

Inspectors log updated. SDS sheets on site in DBG construction trailer.

If construction ceases on the site for more than 14 days, the site must be stabilized until construction resumes.

Date Construction Stopped

☐

Date Construction Resumed

☐

Measures Taken to Stabilize the Site:

Construction Phasing

Verify what stage of construction the project is in, and record dates when activities started and were completed.

Installed BMPs

Started

Started:

08/20

Completed:

08/20

Site Clearing and Grading

Started

Started:

08/20

Completed:

01/21

Installing Utilities

Started

Started:

04/21

Completed:

☐



INSPECTIONS PLUS

General Permit SWPPP Inspection

Site Name:	<u>Ceja Vista Senior Apartments</u> <u>10001 Ceja Vista Rd SW, Albuquerque, NM 87121</u>	Inspector:	Jeff Hart
Permit #:	NMR10032D	Inspection Frequency:	Bi-weekly -
Date of Visit:	Jun 4, 2021, 11:42:02 AM	Last Rain Event Tuesday, June 1, 2021, 0.0"	Last Precipitation Friday, June 4, 2021, 0.07" 48h Forecast 19% Chance of Rain

Building Structure

Started

Started:

04/21

Completed:

☐

Paving and Walks

Not Started

Started:

☐

Completed:

☐

Final Grading/Stabilize Site

Started:

☐

Completed:

☐

Other

Started

Started:

Perimeter retaining walls 02/21

Site-specific BMPs

The corrective actions initiated and date completed are in the Corrective Action Log

List of BMPs Installed:

Silt Fence, Earth Berm, Retaining Wall, Staging Area, Stabilized Access Point- Street in place 98th to fractured rock pad access, wattles at southeast access point, Retaining walls.

Are all of the above controls installed?

Yes

No

Do any of the above controls need maintenance?

Yes

No



General Permit SWPPP Inspection

Site Name:	<u>Ceja Vista Senior Apartments</u> <u>10001 Ceja Vista Rd SW, Albuquerque, NM 87121</u>	Inspector:	Jeff Hart
Permit #:	NMR10032D	Inspection Frequency:	Bi-weekly -
Date of Visit:	Jun 4, 2021, 11:42:02 AM	Last Rain Event Tuesday, June 1, 2021, 0.0"	Last Precipitation Friday, June 4, 2021, 0.07" 48h Forecast 19% Chance of Rain

If any of the controls have not been installed or require maintenance, please list the control and explain.

Install fractured rock pad on the northeast side access point- sediment transfer to VDA and corresponding inlets. Pictures attached. Repair and maintain drop inlets on the VDA property affected by the sediment transfer from from Ceja vista access points. Install additional BMP protection at the southeast, future access, point. Sediment transfer under wattles to building K on the Valle De Atrisco apartments. Sweep the lot and clear sediment from inlets downhill.

Are the BMPs shown on the map?

☐ Yes ☐ No

Were there any changes to the SWPPP?

☐ Yes ☐ No

Has the SWPPP been updated?

☐ Yes ☐ No

Were the changes to the SWPPP implemented within 7 days?

☐ Yes ☐ No

List any new BMPs needed:

NO changes to the SWPPP document at this time. Install fractured rock access pads at construction access point- NE access, if it remains utilized. Sweep the paved parking lot at the VDA apartments as applicable. Install additional BMP protection at the southeast, future access, point. Sediment transfer under wattles to building K on the Valle De Atrisco apartments. Sweep the lot and clear sediment from inlets downhill.

Notes:

Oversight Issues

A list of corrective actions will be supplied with this inspection.

1. Are all slopes and disturbed areas not actively being worked properly stabilized?



INSPECTIONS PLUS

General Permit SWPPP Inspection

Site Name:	<u>Ceja Vista Senior Apartments</u> <u>10001 Ceja Vista Rd SW, Albuquerque, NM 87121</u>	Inspector:	Jeff Hart
Permit #:	NMR10032D	Inspection Frequency:	Bi-weekly -
Date of Visit:	Jun 4, 2021, 11:42:02 AM	Last Rain Event Tuesday, June 1, 2021, 0.0"	Last Precipitation Friday, June 4, 2021, 0.07" 48h Forecast 19% Chance of Rain

Implemented?

Yes

No

N/A

Maintenance Required?

Yes

No

N/A

2. Are natural resources (e.g., streams, Arroyos, mature trees, etc.) protected with barriers or similar BMPs?

Implemented?

Yes

No

N/A

Maintenance Required?

Yes

No

N/A

3. Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?

Implemented?

Yes

No

N/A

Maintenance Required?

Yes

No

N/A

4. Are discharge points and receiving waters free of any sediment deposits?

Implemented?

Yes

No

N/A

Maintenance Required?

Yes

No

N/A

5. Are storm drain inlets properly protected?

Implemented?

Yes

No

N/A

Maintenance Required?

Yes

No

N/A

6. Is the construction exit preventing sediment from being tracked into the street?

Implemented?

Yes

No

N/A

Maintenance Required?

Yes

No

N/A

7. Is trash/litter from work areas collected and placed in dumpsters?



General Permit SWPPP Inspection

Site Name:	<u>Ceja Vista Senior Apartments</u> <u>10001 Ceja Vista Rd SW, Albuquerque, NM 87121</u>	Inspector:	Jeff Hart
Permit #:	NMR10032D	Inspection Frequency:	Bi-weekly -
Date of Visit:	Jun 4, 2021, 11:42:02 AM	Last Rain Event Tuesday, June 1, 2021, 0.0"	Last Precipitation Friday, June 4, 2021, 0.07" 48h Forecast 19% Chance of Rain

Implemented?

<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A
---	-----------------------------	------------------------------

Maintenance Required?

<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> N/A
------------------------------	--	------------------------------

8. Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?

Implemented?

<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A
---	-----------------------------	------------------------------

Maintenance Required?

<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> N/A
------------------------------	--	------------------------------

9. Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?

Implemented?

<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A
---	-----------------------------	------------------------------

Maintenance Required

<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> N/A
------------------------------	--	------------------------------

10. Are materials that are potential storm water contaminants stored inside or under cover?

Implemented?

<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A
---	-----------------------------	------------------------------

Maintenance Required?

<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> N/A
------------------------------	--	------------------------------

11. Are non-storm water discharges (e.g., wash water, dewatering) properly controlled?

Implemented?

<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A
---	-----------------------------	------------------------------

Maintenance Required?

<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> N/A
------------------------------	--	------------------------------

12. Has the Site map been updated to reflect current conditions?

Implemented?

<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A
---	-----------------------------	------------------------------

Maintenance Required?

<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> N/A
------------------------------	--	------------------------------

13. Is the NOI posted?



INSPECTIONS PLUS

General Permit SWPPP Inspection

Site Name:	<u>Ceja Vista Senior Apartments</u> <u>10001 Ceja Vista Rd SW, Albuquerque, NM 87121</u>	Inspector:	Jeff Hart
Permit #:	NMR10032D	Inspection Frequency:	Bi-weekly -
Date of Visit:	Jun 4, 2021, 11:42:02 AM	Last Rain Event Tuesday, June 1, 2021, 0.0"	Last Precipitation Friday, June 4, 2021, 0.07" 48h Forecast 19% Chance of Rain

Implemented?

☒ Yes☐ No☐ N/A

Maintenance Required?

☐ Yes☒ No☐ N/A

14. Were previous corrections made within 7 days of last inspection or before the next storm event?

Implemented?

☐ Yes☒ No☐ N/A

Maintenance Required?

☒ Yes☐ No☐ N/A

Walk through facility and look for signs of pollution including paint, solvents, chemicals, solid waste, oil, and fuel.

Are there any signs of hazardous materials being exposed to storm water runoff?

☐ Yes☒ No

Have there been any reportable quantities releases of hazardous materials?

☐ Yes☒ No

Additional Notes

Certification & Signatures

Certification Statement:

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Electronic Signature

X *Jeff Hart*

Date

June 4, 2021 at 11:45:53 AM MDT

Title
Senior Inspector



INSPECTIONS PLUS


General Permit SWPPP Inspection

Site Name:	<u>Ceja Vista Senior Apartments</u> <u>10001 Ceja Vista Rd SW, Albuquerque, NM 87121</u>	Inspector:	Jeff Hart
Permit #:	NMR10032D	Inspection Frequency:	Bi-weekly -
Date of Visit:	Jun 4, 2021, 11:42:02 AM	Last Rain Event Tuesday, June 1, 2021, 0.0"	Last Precipitation Friday, June 4, 2021, 0.07" 48h Forecast 19% Chance of Rain

Weather History



May



June



All precipitation totals are obtained from the National Oceanic and Atmospheric Administration (NOAA). Precipitation readings are based on the latitude and longitude for each site as entered into complianceGO. Occasionally NOAA fails to return/record data. Days where this occurs are so indicated.



INSPECTIONS PLUS

General Permit SWPPP Inspection

Site Name:	<u>Ceja Vista Senior Apartments</u> <u>10001 Cēja Vista Rd SW, Albuquerque, NM 87121</u>	Inspector:	Jeff Hart
Permit #:	NMR10032D	Inspection Frequency:	Bi-weekly -
Date of Visit:	Jun 4, 2021, 11:42:02 AM	Last Rain Event Tuesday, June 1, 2021, 0.0"	Last Precipitation Friday, June 4, 2021, 0.07" 48h Forecast 19% Chance of Rain

There Are No Action Items