



# City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

Project Name:	Jabil/Ethicon South Arroyo Drainage Improvements				
Location:	3801 University Blvd SE				
Site Contact Name & Agency	Sonya Woodhouse Facility Manager	ESC File No.	P15E003		
	<a href="mailto:sonya_woodhouse@jabil.co">sonya_woodhouse@jabil.co</a>	NPDES Id. No.	NMR1002UF		
Inspection Date:	09/25/20	Start/End Time:	12:15		
CoA Stormwater Inspector:	Doug Hughes				
Construction Phase:	Infrastructure Construction				
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	88
Estimated date of last storm 0.25" or greater	9/1/2020		

Item Number	Deficiency/ Corrective Action		
1	Final stabelization is Complete, Please file NOT.		
2.1	Discharge off site? (Y/N)	no	
3	Self Inspection Reports		Latest report Date: 7/9/2020

Notes:	

City of Albuquerque Stormwater Inspector Signature and date: 9/28/20

Contact information: Doug Hughes (505) 924-3420

[jhughes@cabq.gov](mailto:jhughes@cabq.gov)

*James D. Hughes*