



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	United Poly Systems				
Location:	5201 Hawking SW Bldg B				
Site Contact Name & Agency	Todd - Tanglewood	ESC File No.	Q16E5000		
	toddg@tanglewoodconstruction.com	NPDES Id. No.	NMR1002AX		
Inspection Date:	08/27/19	Start/End Time:	0920/1000hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	vertical				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Post Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	80*
Estimated date of last storm 0.25" or greater	7/7/2019		

Item Number	Deficiency/ Corrective Action		
	no issues observed		
	***please provide latest SWPPP self-inspection report.		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date: none on file

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 08/27/19