

## City of Albuquerque Stormwater Construction Site Inspection Report

			General	Information				
ESC File No.	R16E003C		Project Name:		MDS Montage 6			
NPDES Id. No.	NMR10062Y Lo		Location:		University and Bobby Foster			
12/9/2025		Owner			Contractor			
Operator		Cuesta Del Oro LLC			Twilight Homes			
Contact name & title		Tim McNaney			Tim McNaney			
e-mail		tmcnaney@twilighthomesnm.com			tmcnaney@twilighthomesnm.com			
Contact Phone #		505-975-7754			505-975-7754			
COA Inspector		Chancellor English			Start/End Time	10:30-	11am	
Construction Phase:		verticals						
Type of Ir	nspection:	Regular	Storm Event	Post Storm I	vent >0.25"	311/Complaint	Follow Up	
Weath	er at time of in	nspection? Clear			Temperature: ~ 60			
Estimated	date of last st	torm 0.25" or greater			11/23/2025			
Item			D . C	. / 6				
Number			Deticien	cy/ Correctiv	e Action			
1	Track-out - There is heavy sediment deposit on paved surfaces due to track-out from hauling dirt in							
	violation of CGP Part 2.2.4. Required mitigation: Use appropriate stabilization techniques at all points							
	that exit onto paved roads per CGP Part 2.2.4.b. Where sediment has been tracked-out from your site							
	onto paved roads, sidewalks, or other paved areas outside of your site, remove the deposited							
	sediment by the end of the same business day in which the track-out occurs or by the end of the next							
	business day if the track-out occurs on a non-business day				•			
	·							
	from hosing or sweeping tracked out material into any constructed or natural site drainage feature,							
	storm drain inlet, or receiving water.							
2	Washout - Concrete washout is leaking from the washout container, and there are spots of washout							
	occuring on bare soil in violation of CGP Part 2.3.4. Required mitigation: Direct wash water into a leak-							
	proof container or a leak-proof and lined pit designed so no overflows can occur due to inadequate							
	sizing or precipitation per CGP Part 2.3.4. Do not allow liquid wastes to be disposed of through							
	infiltration or to otherwise be discharged on the ground.							
	inintration or to	o otnerwise	be discharged on	the ground.				
2.1	Discharge off site?	(Y/N)	no	1				
4	Self Inspecti			Latest rep	ort Date:	11/17/2	2025	
4	Jen mspecu	ion keports		Latestie	on t Date.	11/1//	2023	

Notes:				
The posting and SWPPP are located at the very northwestern corner of Montage 6 (Bobby Foster				
construction entrance)				

City of Albuquerque Stormwater Inspector Signature and date: 12/9/2025

Contact information: Chancellor English (505) 924-3325

cenglish@cabq.gov

Chancellor English