

City of Albuquerque Stormwater Construction Site Inspection Report

			General Ir	formation				
Project Name:		Mesa del Sol Montage Unit 3B						
Location:		University and Strand Loop						
Site Contact Name &		Michael Fietz - The Westway ESC File No. R16E006						
Agency		mikef@thewestway.com NPDES Id. No.						
Inspection	Date:	08/13/20 Start/End Time: 0730/0745hrs						
	water Inspecto	r: T	imothy E. Sims					
	ction Phase:	home construction						
Type of Inspection: x		Regular	Storm Event	Post Storm	Event >0.25"	311/Complaint	Follow Up	
Weather at time of i				ar			73*	
Estimated	date of last s	torm 0.25" o	r greater			7/25/2020		
Item								
	Deficiency/ Corrective Action							
Number								
	no issues observed on this inspection							
	Please provide latest SWPPP self-inspection report.							
2.1	Discharge off site?	(Y/N)	No					
4	Self Inspect	tion Reports	requested	Latest re	port Date:			

Notes:	inspection conducted adhering to Covid-19 constraints				

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155