

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Nar	ne:	Mesa del Sol Montage Unit 3B					
Location:		University and Strand Loop					
Site Contact Name &		Michael Fietz - The Westway ESC File No. R16E006					
Agency		mikef@the	ewestway.com	NPDES Id. No.			
Inspection Date:		12/30/19		300/0900hrs			
CoA Stormwater Inspector: Timothy E. Sims							
Construction Phase:					nstruction		
Type of Ir	spection: x	Regular	Storm Event	Post Storm E	vent >0.25"	311/Complaint	Follow Up
Weath	er at time of i	nspection?	Clea	ar	Tempe	rature: ~	33*
Estimated	imated date of last storm 0.25" or greater 11/27/2019						
Item							
Number	Deficiency/ Corrective Action						
Number							
	no issues observed on this inspection						
	Please provide latest SWPPP self-inspection report.						
2.1	Discharge off site?	(Y/N)	No				
				1 - 1 1		7/26/26	14.0
4	Self Inspect	ion Report	s requested	Latest rep	ort Date:	7/26/20)19
Notes:							

 ${\bf City\ of\ Albuquerque\ Stormwater\ Inspector\ Signature\ and\ date:}$

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

12/30/19 _____