



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Montage Unit 3 B Pulte				
Location:	Mesa Del Sol				
Site Contact Name & Agency	Troy - pulte	ESC File No.	R16E006_P		
	troycrutchfield2@pulte.com	NPDES Id. No.	NMR1002K1		
Inspection Date:	08/13/20	Start/End Time:	0800/0830hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	home construction				
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection?	clear	Temperature: ~	73*
Estimated date of last storm 0.25" or greater	7/25/2020		

Item Number	Deficiency/ Corrective Action		
	no issues observed with this inspection		
	Please forward the latest SWPPP self-inspection report.		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date:

Notes:	inspection conducted adhering to Covid-19 constraints

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 08/13/20