

City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:		Montage Unit 3 B Pulte					
Location:		Mesa Del Sol					
Site Contact Name & Agency	Troy - pulte			ESC File No.	R16E006_P		
	troycrutchfield2@pulte.com			NPDES Id. No.	NMR1002K1		
Inspection Date:	12/30/19	Start/End Time:	0900/1000hrs				
CoA Stormwater Inspector:		Timothy E. Sims					
Construction Phase:		home construction					
Type of Inspection:	x	Regular	Storm Event	Post Storm Event >0.25"	311/Complaint	Follow Up	

Weather at time of inspection?	clear	Temperature: ~	33*
Estimated date of last storm 0.25" or greater	11/27/2019		

Item Number	Deficiency/ Corrective Action			
1	Please provide a copy of the NOI posted on site.			
2	Please provide latest SWPPP self-inspection report.			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports	requested	Latest report Date:	not on file

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 12/30/19