



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	R16E006_P	Project Name:	Mesa Del Sol Unit 3B
NPDES Id. No.	NMR1002K1	Location:	Strand Loop and Dekooning Ave. SE
Operator	Owner	Contractor	
Contact name & title	Pulte Homes	Pulte Homes	
e-mail	Dan Mallak	Troy Crutchfield	
Contact Phone #	dan.mallak@pultegroup.com	troycrutchfield2@pulte.com	
COA Inspector	505-554-6273	Start/End Time:	
Thomas Evans			
Construction Phase:	Home construction		
Type of Inspection:	Regular	Storm Event	Past Storm Event >0.25"
		311/Complaint	Follow Up
Weather at time of inspection?	rain	Temperature: ~	60
Estimated date of last storm 0.25" or greater	2/22/2021		
Item Number	Deficiency/ Corrective Action		
1	Re-attach SWPPP permit posting to pole		
2	Remove and dispose of construction waste		
3	Repair waste containers		
4	Remove and dispose of washout. Use proper washout procedures		
5	Remove sediment from the streets		
6	Maintain silt fences/BMPs		
7	Provide latest self-inspection report		
2.1	Discharge off site? (Y/N)	no	
4	Self Inspection Reports	Requested	Latest report Date:

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Thomas Evans (505-803-6215)
tevans@cabq.gov

Thomas Evans 04/28/2021