



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	R16E006_P	Project Name:	Mesa Del Sol Unit 3B		
NPDES Id. No.	NMR1002K1	Location:	Strand Loop and Dekooning Ave. SE		
2/4/2022	Owner	Contractor			
Operator	Pulte Homes	Pulte Homes			
Contact name & title	Dan Mallak	Matt Sena			
e-mail	dan.mallak@pultegroup.com	troycrutchfield2@pulte.com			
Contact Phone #	505-554-6273	603-7159			
COA Inspector	Doug Hughes	Start/End Time:	2pm		
Construction Phase:	Home construction				
Type of Inspection:	Regular	Storm Event	Past Storm Event >0.25"	311/Complaint	Follow Up
Weather at time of inspection?		rain		Temperature: ~ 26	
Estimated date of last storm 0.25" or greater		1/1/2022			
Item Number	Deficiency/ Corrective Action				
1	none				
2					
3					
4					
5					
6					
7					
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Requested	Latest report Date:		

Notes:	
2 houses remain. Posting and SWPPP at models.	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Doug Hughes
jhughes@cabq.gov

2/16/2022
James D. Hughes