NOTE: 2016 Protocol - Maximum of one SSWR per permit

PROPRIETARY COMPANY MATERIAL



Date & Time: <u>06-10-2021 at 5:34 PM</u>

NATIONAL STORM WATER QUALITY PROGRAM SITE INSPECTION REPORT (SIR)

For use on most PulteGroup Sites as of 01/01/2016

Community Name:		Pulte: Mesa Del Sol U	Pulte: Mesa Del Sol Unit 3 B, Albuquerque, NM NPDES: NMR1002K1						
		(Include Site Name, Ci	ty, State, Zip Code and NPDES/	Construction Storm Water Perm	it Number)				
Master Site List ID:			Inspection performed by: Mario Alderete, Inspector, Green Globe Environmental						
				(Print Na	ame, Company, and Title / Qua	lifications)			
Stages o	of Construction:	(check all that apply)	Land Development	Inactive	Vertical Construction	Post-Construction			
Type of	Inspection:	(check all that apply)	Routine Inspection Other:	Storm-Event Related	Final Site Inspection				
I.	SWPPP - Respond	d to all Questions							
Item	•	•			Yes	No			
A	Was the SWPPP accessible at the time of the inspection?				\Box	If "No," then an Action			
В	Is the SSWR correctly identified in the SWPPP?				$\overline{\boxtimes}$	Item is required.			
С	Does the SWPPP ref	lect the current stage of develor	oment?		₩	Describe all Action Items on the reverse side of this sheet. (Section IV)			
D	Have all SIR action	Items identified on the precedin	g reports been resolved?						
E	Is NSQP Signage po	sted and in compliance with NS	SQP requirements?		$\overline{\boxtimes}$				
II.	Estimated date of most recent Storm Event That triggered an Inspection: 11-07-2020								
	Provide rainfall info	ormation as required by the App	licable Permit: <u>.25 Inches</u>		(Base on the storm-event related Inspection Frequency required by the Applicable Permit)				
III.	Site BMP Inspecti	ion	Not						
<u>Item</u>	SWPPP Items		<u>Applicable</u>	<u>Acceptable</u>	Action Item	Assigned To			
Erosion	1 Control								
1	Protection of Distur	bed Areas		\boxtimes					
2	Slope Protection		$\overline{\boxtimes}$						
3	Vegetation / Revege	tation							
4	Velocity Reduction	Devices / Outlet Protection	\boxtimes						
Sedime	nt Control								
5	Check Dams (rock, g	gravel, other)	П	\boxtimes					
6	Silt Fence			$\overline{\boxtimes}$					
7	Berms, Dikes, Straw	Wattles	$\overline{\boxtimes}$						
8	Detention Basins/Se	ediment Traps							
9	Stockpiles Protected	d/Stabilized		\boxtimes					
10	Storm Water Inlet Pr	rotection	\boxtimes						
Housek	eeping / Trade Com	npliance							
11	Waste and Trash Ma	nagement		\boxtimes					
12	Spill and Leak Preve	ention		$\overline{\boxtimes}$					
13	Sanitary Stations			$\overline{\boxtimes}$					
14	Concrete and Constr	ruction Washouts		\boxtimes					
15	Material Use and Po	laterial Use and Potential Contaminate Storage							
16	Equipment Storage	and Maintenance							
17	Construction Exits a	and Entrances		\boxtimes					
18	Dust Control								
19	Street Sweeping			\boxtimes					

PROPRIETARY COMPANY MATERIAL

Not <u>Item</u> SWPPP Items (continued) **Applicable Acceptable Action Item** Assigned To Other 20 Non-Storm Water Flow 21 Site's Weathering of Storm Events 22 Site Discharge Points 23 BMP Provider Performance X IV. **Action Items** V. Responsive Action Completion Item Location and Responsive Action to be taken **Date Noted Date of Completion Initials** Deficiency Name: 2604 houser 23 06-10-2021 Corrective Action: Cut curb back

Attach additional sheet(s) of SIR addendum if necessary

SIR must be reviewed and signed below by SSWR - Not Delegable: I certify under penalty of law that Sections I-V of this document and all attachments were prepared by me or under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. In the event there are no Action Items in this report that have remained unresolved for a period in excess of that allowed by the Applicable Construction General Permit, I further certify under penalty of law that this Site is in compliance with the SWPPP and the Applicable Construction General Permit. I am aware that there are significant penalties for submitting false information including the possibility of fine and imprisonment for knowing violations. Certification applies to the area under the supervision of the SSWR signing this report.

ertified By: (SSWR - Must be a PulteGroup Employee)		Certified By: (Third Party Inspector if required by the Applicable Permit)				
		Mario Alderete				
ite Storm Water Representative - Print Name and Title		Inspector - Print Name				
		March Slate				
Site Storm Water Representative Signature (Use Ink) Date		Inspector Signature (Use Ink)	Date			
Justification for non-completion of Responsive Actions						
Describe why any Responsive Actions were not corrected within the permit required time period (if applicable).						

Attach additional sheet(s) if necessary