Westway Homes

Westway Homes: Mesa Del Sol Unit B

Storm Water Compliance Inspection Form



PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

Inspection Type: Routine	Date: 04-15-2021	Time: 9:20 AM		
Permit Tracking #: NMR1003BG	Inspector Name: Mario Alderete	Qualifications: Inspector		
Current Weather Conditions:	Date and Amount of Last Recordable Storm Event:			

Construction Time Line:

Action	Start Date	Date Complete
Initial BMP Installation		
Clearing and Grubbing		
Utility Installation		
Construction of Structure		
Final Stabilization		

Site Walk:

Question	Yes	No	N/A	Comment
Is there a proper posting sign?			\boxtimes	We have the sign just need to know where they want it posted.
Are areas that have been disturbed, but not under construction been properly stabilized?			\boxtimes	
Velocity Reduction Devices i.e. Check Dams, Berms, Etc.			\boxtimes	
Silt Fence		\boxtimes		
Wattles/Filter Sock			\boxtimes	
Inlet Protection			\boxtimes	
Cut Back Curbs	\boxtimes			
Waste Management	X			
Vehicle Tracking Control			\boxtimes	
Material Storage			\boxtimes	
Dust Control	X			
Street Sweeping		\boxtimes		
Construction Washouts i.e. Concrete, Paint, Stucco Etc.		\boxtimes		
Discharge Points	\boxtimes			
Sanitary Stations	\boxtimes			
Stockpiles			\square	
Other				

Westway Homes

Westway Homes: Mesa Del Sol Unit B

NMR1003BG

SWPPP Information:

Question	Yes	No	N/A	Comment
Is the SWPPP kept on site?		Χ		
Was the SWPPP updated at the time of the inspection?		\boxtimes		
Are all certification pages signed?			Χ	
Are inspector qualifications in the SWPPP?	\boxtimes			
Is there a copy of the NOI and Acknowledgement letter?	\boxtimes			
Is there a delegation letter in the SWPPP?	\boxtimes			
Was the last inspection/CAL certified?			\boxtimes	This is the first inspection conducted by Green Globe

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Owner: Westway Homes

Name

Operator:

Signature

Signature

Date

Date

Additional Comments:

Name

Westway Homes: Mesa Del Sol Unit B



Action Log:

Location	Action Type	Action Required	Date Noted	Date Completed	Initials
5519 De Kooning	Maintenance	Need to remove/replace the silt fence	11-01-2020		
2501 de Kooning	Maintenance	Need to replace/remove the silt fence	11-15-2020		
Motherwell	Maintenance	Need to sweep the street	10-18-2020		
Strand Loop	Maintenance	Need to sweep the street	11-01-2020		
De Kooning	Maintenance	Need to sweep the street	11-15-2020		
Witkin	Maintenance	Need to sweep the streey	11-15-2020		
Okeefe	Maintenance	Need to sweep the street	12-13-2020		
6135 Motherwell	Maintenance	Need to clean up the washout on the lot	10-18-2020		
6101 motherwell	Corrective Action	Need to clean up concrete washout	03-04-2021		

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

 $\omega_{cos} \mathcal{A}_{d}$ \mathcal{L}

Inspector: Mario Alderete Name

Signature

04-15-2021

Date