

Storm Water Compliance Inspection Form

PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

Inspection Type: Routine Date: 07-15-2021 Time: 9:27 AM

Permit Tracking #: Inspector Name: Mario Alderete Qualifications: Inspector

Current Weather Conditions: Date and Amount of Last Recordable Storm Event:

Thunderstorms (Chance)

Construction Time Line:

Action	Start Date	Date Complete
Initial BMP Installation	06-04-2021	
Clearing and Grubbing	06-11-2021	
Utility Installation		
Construction of Structure		
Final Stabilization		

Site Walk:

Question	Yes	No	N/A	Comment
Is there a proper posting sign?	\boxtimes			
Are areas that have been disturbed, but not under construction been properly stabilized?				
Velocity Reduction Devices i.e. Check Dams, Berms, Etc.				
Silt Fence		\boxtimes		
Wattles/Filter Sock			\boxtimes	
Inlet Protection	\boxtimes			
Cut Back Curbs			\boxtimes	
Waste Management	\boxtimes			
Vehicle Tracking Control	\boxtimes			
Material Storage	\boxtimes			
Dust Control	\boxtimes			
Street Sweeping	\boxtimes			
Construction Washouts i.e. Concrete, Paint, Stucco Etc.		\boxtimes		
Discharge Points	\boxtimes			
Sanitary Stations	\boxtimes			
Stockpiles	\boxtimes			
Other			\boxtimes	

Corazon Del Mesa 4, LLC Corazon Del Mesa 4, LLC:

Mesa Del Sol Montage Unit

4

SWPPP Information:

Question	Yes	No	N/A	Comment
Is the SWPPP kept on site?		\boxtimes		
Was the SWPPP updated at the time of the inspection?				
Are all certification pages signed?			\boxtimes	
Are inspector qualifications in the SWPPP?			\boxtimes	
Is there a copy of the NOI and Acknowledgement letter?				
Is there a delegation letter in the SWPPP?			\boxtimes	
Was the last inspection/CAL certified?			\boxtimes	
personnel properly gathered and evaluated the information subm	nitted. Bas e best of n	ed on my i ny knowle	nquiry of th dge and be	direction or supervision in accordance with a system designed to assure that qualified to person or persons who manage the system, or those persons directly responsible lief, true, accurate, and complete. I am aware that there are significant penalties for tions."

Date

Date

Name Additional Comments:

Name

Operator:

Signature

Signature

Corazon Del Mesa 4, LLC Corazon Del Mesa 4, LLC:

Mesa Del Sol Montage Unit

4



Action Log:

Location	Action Type	Action Required	Date Noted	Date Completed	Initials			
West perimeter	Maintenance	Need to repair small sections along west perimeter	07-08-2021					
Concrete washout pit	Corrective Action	Need to install sign for concrete washout	07-08-2021					
Swppp book is with field manager			06-18-2021					

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Inspector: Mario Alderete

07-15-2021

Name Signature Date