

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No.	R16E0	06C Project Name:			Montage Unit 5		
NPDES Id. No. NMR10		062N Location:			Bobby Foster and University		
	4/2025	Owner			Contractor		
Operator		Titan Montage 5			Guzman		
Contact name & title		Brian Patterson			Eddie Gonzales		
		bpatterson@titan-development.com			eddie@guzmancs.com		
Contact Phone #		505-238-0700			505-452-0663		
COA Inspector		Chancellor English			Start/End Time:	1145am	
Construction Phase:		Beginning verticals, utilities					
Type of In		Regular Storm Event Past Storm Event >0.25" 311/Complaint Follow Up					
Weather at time of i		nspection?	clea	r	Tempera	ture: ~ 65	
Estimated	date of last s	torm 0.25" c	or greater		11/7/2025		
Item	Deficiency/ Corrective Action						
Number							
1	BMPs - The perimeter silt fencing along the western and southern borders have collapsed and need						
	maintenance/repair/replacement in violation of CGP Part 2.1.4. Required mitigation: Ensure all						
	stormwater controls are maintained and remain in effective operating condition during permit						
	coverage and are protected from activities that would reduce their effectiveness per CGP Part 2.1.4.						
	coverage and are protected from activities that would reduce their effectiveness per CGP Part 2.1.4.						
2.4	Disabassa W ii 2	(\/\frac{1}{2}					
2.1	Discharge off site?	(Y/N)	no	1 - 1 1		2/40/2025	
4	Self Inspect	ion Reports	Yes	Latest re	port Date:	3/10/2025	
Notes:							
Amend the SWPPP as properties are sold or operational control is transferred.							
The SWPPP is in a doc-box mounted on the back of the posting.							

City of Albuquerque Stormwater Inspector Signature and date: 3/26/2025

Contact information: Chancellor English 505-924-3325

cenglish@cabq.gov

Chancellor English