

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	R16E006				Mesa Del Sol Montage 5			
NPDES Id. No. NMR 10					Scholer Ave and Groman Ave SE			
7/30/2025		Owner			Contractor			
Operator		DR Horton						
Contact name & title		Tom Totaro						
e-mail		<u>tjtotaro@drhorton.com</u>						
Contact Phone #		505-797-4245						
COA Inspector		Chancellor English			Start/End Time: 11:30am			
Construction Phase:					nding		_	
Type of Inspection:		Regular	Storm Event	Post Storm I	Event >0.25"	311/Complaint	Follow Up	
Weather at time of i		·			Temperature: ~ 90			
Estimated	date of last s	torm 0.25" (	orm 0.25" or greater			7/3/2025		
Item	Deficiency/ Corrective Action							
Number	2555577 555785							
1	None - Posting and SWPPP were placed on-site just prior to inspection.							
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspect	ion Reports	No	Latest rep	oort Date:	N/A		
Notes:								
According to tax records, property is still owned by Titan Montage 5 LLC								
		,, , ,	·		<u> </u>			
	City of All	huguarana C+	cormwater Inchest	or Cianatura	and data:			
City of Albuquerque Stormwater Inspector Signature and date:								
Contact information: Chancellor English (505) 924-3325								

cenglish@cabq.gov