

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.			Project Name:		SD O-7 MDS			
NPDES Id. No. NMR1004DT &		NMR1004D0L	ocation:		Stryker/ Fellini St			
2/4/2022		Owner			Contractor			
Operator		SC3 Development			Guzman			
Contact name & title		Tom Schmidt			Pena Altagracia			
Contact Phone #		tom@SC3development.com			Lupita@guzmanSCS.com			
Contact Phone #		David Hughan			452-0663			
COA Inspector		Doug Hughes			Start/End Time: 1:50 PM/2:00 PM			
Construction Phase:					tructure		1	
	spection:	Regular	Storm Event			311/Complaint	Follow Up	
Weather at time of i			cloud	dy	Tempera	iture: ~	26	
Estimated date of last storm 0.25" or greater 1/1/2022								
Item			- 6.					
Number	Deficiency/ Corrective Action							
	A.I							
1	None.							
2								
3								
,								
4	Please provide latest self inspection report.							
5								
2.1	Discharge off site?	(Y/N)	no					
	_			l atast see	nort Dots:			
4	Seit inspect	tion Reports	Requested	Latest re	port Date:			
Nata:								
Notes:								

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug hughes (505) 924-3420

jhughes@cabq.gov

2/10/2022

James D. Hughes