Enterprise Builders: Mesa Del Sol International School



Storm Water Compliance Inspection Form

PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

Inspection Type: Routine Date: 07-20-2021 Time: 11:05 AM

Permit Tracking #: Inspector Name: Mario Alderete Qualifications: Inspector

Current Weather Conditions: Date and Amount of Last Recordable Storm Event: 05-31-2021 .5

Construction Time Line:

Action	Start Date	Date Complete					
Initial BMP Installation	02-26-2021						
Clearing and Grubbing	02-26-2021						
Utility Installation							
Construction of Structure	07-20-2021						
Final Stabilization							

Site Walk

Site waik.				
Question	Yes	No	N/A	Comment
Is there a proper posting sign?	\boxtimes			North west entrance
Are areas that have been disturbed, but not under construction been properly stabilized?				
Velocity Reduction Devices i.e. Check Dams, Berms, Etc.				
Silt Fence		\boxtimes		Perimeter
Wattles/Filter Sock			\boxtimes	
Inlet Protection			\boxtimes	
Cut Back Curbs			\boxtimes	
Waste Management			\boxtimes	
Vehicle Tracking Control	\boxtimes			
Material Storage			\boxtimes	
Dust Control	\boxtimes			Water truck onsite
Street Sweeping	\boxtimes			
Construction Washouts i.e. Concrete, Paint, Stucco Etc.				
Discharge Points			\boxtimes	
Sanitary Stations	\boxtimes			
Stockpiles	\boxtimes			
Other			\boxtimes	

Enterprise Builders

Question

Signature

Enterprise Builders: Mesa Del Sol International School

N/A

Comment

Date

No

SWPPP Information:

Is the SWPPP kept on site?				
Was the SWPPP updated at the time of the inspection?				SWPPP book not on site
Are all certification pages signed?				
Are inspector qualifications in the SWPPP?				
Is there a copy of the NOI and Acknowledgetter?	gement		\boxtimes	
Is there a delegation letter in the SWPPP?			\boxtimes	
Was the last inspection/CAL certified?			\boxtimes	
personnel properly gathered and evaluated the info	rmation submitted. Basitted is, to the best of	sed on my my knowle	inquiry of t dge and be	direction or supervision in accordance with a system designed to assure that qualifie the person or persons who manage the system, or those persons directly responsible slief, true, accurate, and complete. I am aware that there are significant penalties for ations."
Name Sigr	ature			Date
Operator:				

Name
Additional Comments:

Enterprise Builders

Enterprise Builders: Mesa Del Sol International School



Name

Action Log:

Location	Action Type	Action Required	Date Noted	Date Completed	Initials
North perimeter	Corrective Action	Silt fence needs to be stood back up	06-15-2021		
West perimeter	Corrective Action	Silt fence needs repair	06-15-2021		

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Date

Inspector: Mario Alderete 07-20-2021

Signature



3/2/21





3/16/21



3/23/21



3/30/21



4/6/21



4/12/21



4/20/21



4/27/21





5/25/21





6-15-21



6-22-21



6/29/21