### Enterprise Builders: Mesa Del Sol International School



## **Storm Water Compliance Inspection Form**

PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

Inspection Type: Routine Date: 06-22-2021 Time: 1:25 PM

Permit Tracking #: Inspector Name: Joshua Armijo Qualifications: Inspector

Current Weather Conditions: Date and Amount of Last Recordable Storm Event: 05-31-2021 .5

#### **Construction Time Line:**

Action	Start Date	Date Complete						
Initial BMP Installation	02-26-2021							
Clearing and Grubbing	02-26-2021							
Utility Installation								
Construction of Structure								
Final Stabilization								

#### Sita Walk.

Site waik.				
Question	Yes	No	N/A	Comment
Is there a proper posting sign?	$\boxtimes$			North west entrance
Are areas that have been disturbed, but not under construction been properly stabilized?				
Velocity Reduction Devices i.e. Check Dams, Berms, Etc.				
Silt Fence		$\boxtimes$		Perimeter
Wattles/Filter Sock			$\boxtimes$	
Inlet Protection			$\boxtimes$	
Cut Back Curbs			$\boxtimes$	
Waste Management			$\boxtimes$	
Vehicle Tracking Control	$\boxtimes$			
Material Storage			$\boxtimes$	
Dust Control	$\boxtimes$			Water truck onsite
Street Sweeping	$\boxtimes$			
Construction Washouts i.e. Concrete, Paint, Stucco Etc.				
Discharge Points			$\boxtimes$	
Sanitary Stations	$\boxtimes$			
Stockpiles	$\boxtimes$			
Other			$\boxtimes$	

# **Enterprise Builders**

Question

Signature

### Enterprise Builders: Mesa Del Sol International School

N/A

Comment

Date

No

#### **SWPPP Information:**

Is the SWPPP kept on sit	e?	$\boxtimes$			
Was the SWPPP updated inspection?					No one from Enterprise Builders on site
Are all certification pages	signed?				
Are inspector qualification	ns in the SWPPP?				
Is there a copy of the NC letter?	I and Acknowledgement				
Is there a delegation lette	r in the SWPPP?				
Was the last inspection/C	AL certified?				
personnel properly gathered ar for gathering the information, t	nd evaluated the information subn	nitted. Bas e best of r	ed on my ny knowle	inquiry of t dge and be	direction or supervision in accordance with a system designed to assure that qualifie the person or persons who manage the system, or those persons directly responsible slief, true, accurate, and complete. I am aware that there are significant penalties for ations."
Owner:					
Name	Signature				Date
Operator:					

Name
Additional Comments:

#### **Enterprise Builders**

### Enterprise Builders: Mesa Del Sol International School



#### **Action Log:**

Location	Action Type	Action Required	Date Noted	Date Completed	Initials
North perimeter	Corrective Action	Silt fence needs to be stood back up	06-15-2021		
West perimeter	Corrective Action	Silt fence needs repair	06-15-2021		

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

 Inspector:
 Joshua Armijo
 06-22-2021

 Name
 Signature
 Date



3/2/21





3/16/21



3/23/21



3/30/21



4/6/21



4/12/21



4/20/21



4/27/21





5/25/21





6-15-21



6-22-21