

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No.	. R16E100A		Project Name:	DR Horton at Montage Unit 7			
NPDES Id. No.	NMR1005MV		Location:	2101 Stieglitz Ave SE			
3/2-1/		Owner -			Contractor		
Operator		DR Horton F			DR Horton Homes		
Contact name & title		Joseph Cordero					
e-mail Contact Phone #		jcordero@drhorton.com 505-991-5266					
COA Inspector		Chancellor English		Start/End Time:	·		
Construction Phase:					nplete, few vacant lots		
Type of Inspection:		Regular	Storm Event			311/Complaint	Follow Up
Weather at time of inspectio			Clea	r	Temperature: ~ 65		
Estimated date of last storm 0.25" or greater 11/7/2024							
Item	Defining out Compating Action						
Number	Deficiency/ Corrective Action						
	None						
1	None						
2.1	Discharge off site?	(Y/N)					
4	Self Inspect	ion Reports	yes	Latest re	eport Date:	3/17/20)25
Notes:					•		

City of Albuquerque Stormwater Inspector Signature and date: 3/25/2025

Contact information: Chancellor English 505-924-3325

cenglish@cabq.gov

Chancellor English