

City of Albuquerque Stormwater Construction Site Inspection Report

	MILLER		General I	nformation				
ESC File No. U13E				1	Tract 7 MDS			
NPDES Id. No.			Location:		9601 Broadway Blvd SE			
3/22/2022		Owner		Contractor				
Operator		MDS Investments, LLC			Guzman Construction Solutions			
Contact name & title		Kyle Bodine			Rudy Guzman			
e-mail		Kyle@sc3intl.com			rudy@guzmancs.com			
Contact Phone #		681-9932			505-459-3128			
COA Inspector		Doug Hughes			Start/End Time: 2:20pm			
Construction Phase: Type of Inspection:					on/grading			
		Regular	Storm Event		Event >0.25"	311/Complaint	Follow Up	
	er at time of i			dy	Tempe		40	
Estimated	date of last s	torm 0.25"	or greater			3/22/2022		
Item			Deficien	w/Correctiv	Action			
Number	Deficiency/ Corrective Action							
1	1 13 Acres cleared and graded without ESC Permits, Posting, BMPs or SWPPP availability. Prepare SWP file NOI, Submit ESC Plan and NOI to the City for approval, Post Construction General Permit coverage and construct and Maintain BMPs per the CGP. Sediment traps, Diversion Berms/swales, Silt Fence, and construction entrance required. Air Quality requirements are in addition to an not instead of							
		nwater Quality concerns.						
2 The initial construction is subject to the CGP and ESC Ordinance including the grading and sta							tabilization	
		nd any required public infrastructure such as frontage improvements, drainage						
	improvements and onsite permanent ponds and swales. If a commercial use is approved by zoning for							
	Construction Materials Storage or a similar Commercial use then a separate Multi-Sector General Permit							
	(MSGP) may be required and the CGP coverage will be terminated after all of the required							
	improvements are completed and the site is stabilized. Alternatively this site may just be a temporary							
	construction site where commercial uses are not allowed and an MSGP won't be required.							
3	Sinco tho cito l	has already l	acon graded the day	nago has alre	ady been den	o Cossation of co	octruction	
	Since the site has already been graded the damage has already been done. Cessation of construction							
	and commercial activities is recommended to prevent further damage until all permits are obtained. The							
	property owner is responsible for mitigating concerns for public safety such as blowing dust, erosion and							
	sedimentation. Watering for dust control and BMP construction for public health and safety and for the							
	protection of adjacent properties is the property owner's responsability.							
The entire	site was clea	red, grade	d and compacted,	one stockpi	ile of earth 15	5' tall by 300' lor	ng was	
			8/14/2022 along w	•		•	-	
-			· · · •			-		
			onsite for about 4	•				
pile was a	dded the next	t day. There	e hadn't been any	noticeable	activity for 5	days at the time	of the	
second ins	spection on 3,	/22/22.						
on 3/15/2	022, I spoke v	with Kyle a	nd sent the first vi	olation noti	ce to him as t	he Point of Con	tact on	
	•	•	aid MDS had a buy					
that deal i								
		3/16/2022	to find out what	needs to be	done and L	avalained the ne	ed for the	
Rudy Guzman called on 3/16/2022 to find out what needs to be done, and I explained the need for the BMP's and Permits and the City's system of escalating penalties. He said he would have E2RC work on								
			system of escalating	ig penaities	. не said ne v	vouid nave E2RC	, work on	
mitigating	the Violation	IS.						