## **PV Valle Prado LLC: Valle** Prado at the Trails units 4 & 5



## **Storm Water Compliance Inspection Form**

PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

Inspection Type: Routine Permit Tracking #: NMR1002C8 Current Weather Conditions: Clear Date: 06-23-2022 Inspector Name: Lorenzo Santistevan

Time: 11:51 AM Qualifications: Compliance Inspector Date and Amount of Last Recordable Storm Event: 07-27-2021 .75 inch

Construction Time Line:

Action	Start Date	Date Complete
Initial BMP Installation	09-25-2019	09-26-2019
Clearing and Grubbing	09-26-2019	
Utility Installation	12-30-2019	
Construction of Structure		
Final Stabilization		

### Site Walk:

Question	Yes	No	N/A	Comment
Is there a proper posting sign?	$\boxtimes$			On temporary fence in staging area
Are areas that have been disturbed, but not under construction been properly stabilized?			$\boxtimes$	
Velocity Reduction Devices i.e. Check Dams, Berms, Etc.			$\boxtimes$	
Silt Fence		$\boxtimes$		
Wattles/Filter Sock			$\boxtimes$	
Inlet Protection			$\boxtimes$	
Cut Back Curbs			$\boxtimes$	
Waste Management	$\boxtimes$			
Vehicle Tracking Control			$\boxtimes$	Paved
Material Storage			$\boxtimes$	
Dust Control	$\boxtimes$			Water truck on site
Street Sweeping	$\boxtimes$			
Construction Washouts i.e. Concrete, Paint, Stucco Etc.			$\boxtimes$	
Discharge Points		$\boxtimes$		
Sanitary Stations	$\boxtimes$			
Stockpiles	$\boxtimes$			Stock piles being used
Other			$\boxtimes$	

# PV Valle Prado LLC: Valle Prado at the Trails units 4

& 5

### SWPPP Information:

Question	Yes	No	N/A	Comment
Is the SWPPP kept on site?	$\boxtimes$			
Was the SWPPP updated at the time of the inspection?	$\boxtimes$			
Are all certification pages signed?	$\boxtimes$			
Are inspector qualifications in the SWPPP?				
Is there a copy of the NOI and Acknowledgement letter?				
Is there a delegation letter in the SWPPP?	$\boxtimes$			
Was the last inspection/CAL certified?				

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Pur Jam

Owner: PV Valle Prado, LLC

Name

Operator: Rico Gallegos

Name

Signature

Signature

Additional Comments:

Date Date

06-23-2022

### PV Valle Prado LLC: Valle Prado at the Trails units 4 & 5



### Action Log:

Location	Action Type	Action Required	Date Noted	Date Completed	Initials
perimeter silt fence	Maintenance	Repair or replace damaged silt fence	03-17-2022		
North/Northeast perimeter north of wall	Maintenance	Repair or replace damaged silt fence	06-23-2022		
North of walls formerly staging area	Maintenance	Need to establish controls for disturbed areas	06-23-2022		

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Inspector: Lorenzo Santistevan

Name

Signature

06-23-2022 Date Site Walk Deficiency Photos - perimeter silt fence





Site Walk Deficiency Photos - North/Northeast perimeter north of wall

